

Instructions for use

Men's short-sleeved T-shirt
Men's long-sleeved T-shirt
Men's short-sleeved POLO shirt
Men's long-sleeved POLO shirt
Short-sleeved sweatshirt

art. 0-0850-907
art. 0-0851-907
art. 0-0852-907
art. 0-0853-907
art. 0-0860-908

Women's short-sleeved T-shirt
Women's long-sleeved T-shirt
Women's short-sleeved POLO shirt
Women's long-sleeved POLO shirt

art. 0-0854-907
art. 0-0855-907
art. 0-0856-907
art. 0-0857-907

Intended use

Protective clothing, anti-electrostatic, consists of garments indicated above. Clothing designed for use in explosive atmosphere where the static electricity may cause ignition. Clothing meets the essential requirements for personal protective equipment contained in the Regulation of the European Parliament and of the EU Council 2016/425 of 9 March 2016 on personal protective equipment and in the standards: EN ISO 13688:2013; EN 1149-5:2018.

Use

Clothing should be used in a complete set with other clothing that meets the standards.

Clothing should always be buttoned during use. For proper protection against static electricity, the user should be properly grounded. The electrical resistance between the human skin and the ground should be less than 108Ω, e.g. by wearing appropriate footwear on distracting or conductive floors. Clothing should not be unzipped and / or removed in flammable or explosive atmospheres and when handling flammable or explosive substances. Clothing is intended to be worn in Zones 1, 2, 20, 21 and 22 in which the minimum ignition energy of each explosive atmosphere is not less than 0.016 mJ. Clothing should not be used in oxygen enriched atmospheres and Zones without the prior approval of the safety engineer. Clothing during normal use (including bending) should completely cover all materials that do not meet the requirements of EN 1149-5:2018.

The clothing should be regularly cleaned as recommended by the manufacturer. Clothes should be checked after cleaning. Each time before use, an employee intending to use clothing should inspect the clothing for damage. If the product inspection reveals that the clothing is damaged, it must be repaired. Clothing can only be repaired by the manufacturer or specialized facilities. Damaged items of clothing (pleats, flaps, front parts or sleeves) should be replaced. Fabrics and threads as well as missing fasteners (buttons, adhesive tapes) used for repairs should be original, supplied by the clothing manufacturer. Clothing after repair should keep its original shapes and dimensions. ATTENTION: A faulty repair can result in the loss of protective properties of clothing. In the event of damage excluding the replacement of elements with new ones, clothing should be immediately removed from use. Do not allow heavy dirt during use.

Storage and transport

The clothing should be transport in original packaging (plastic bags), protecting against dirt, mechanical damage and getting wet. Store the clothing in a dry and well-ventilated place, away from heat sources. Do not store the clothing when it is dirty.

Warnings:

- The properties of clothing, resulting from the requirements of EN 1149-5:2018 (EN 1149-3 method), confirmed after 50 maintenance cycles.
- The effectiveness of the protection provided by clothing can be affected by: wear, damage, washing and possible contamination.
- The personal protection equipment after use is a waste, which the user should properly classify and then transfer for disposal in accordance with applicable law.
- No allergenic substances have been found in the materials used to manufacture the clothing; however, if any allergic reactions are noticed, especially in the case of sensitive individuals, such a person should leave the working zone, take off the garment and consult a doctor.
- It is advisable to keep this manual for further reference.

EU Type Examination Certificate No. **20-A/2018/PPE/1435** issued by notified body no. **1435** – Sieć Badawcza Łukasiewicz - Instytut Włókiennictwa - Zakład Certyfikacji Textil-Cert, ul. Brzezińska 5/15, 91-103 Łódź.





EU Declaration of Conformity at: www.kegel.pl/ce

Composition: Fabric: Polyester 50%, Cotton 49%, Antistatic fiber 1%

 EN 1149-5:2018		
Protection against static electricity	Clothing meets the essential requirements for personal protective equipment, contained in the Regulation of the European Parliament and of the Council of the European Union 2016/425 dated 9 March 2016.	Before using, read the contents of this instructions for use.

Maintenance

Do not wash clothing with other clothing. Use the following maintenance procedures:

			
Maximum washing temp. 40 °C – normal process	Do not bleach	Tumble drying possible – lower temperature. Max. exhaust temp. 60°C	Iron at max. sole-plate temperature of 110°C

Body dimensions to the size of protective clothing

In order to properly choose the size, use the information in the size table.

Size table (dimensions are given in centimeters)

Size	Height (A)		Chest size (B)	
	Men	Women	Men	Women
XS	164-170	158-164	84-88	76-80
S	164-170	158-164	88-92	80-84
M	170-176	158-164	92-96	84-88
L	170-176	164-170	96-100	88-92
XL	176-182	164-170	100-104	92-96
2XL	176-182	170-176	104-108	96-104
3XL	182-188	170-176	108-114	104-108
4XL	182-188	176-182	114-120	108-116

